ECS/EMD Configuration Change Request

Page 1 of Page(s)

1. Originator	2. Log Date:	3. CCR #:	4. Rev:	5. Tel:	6. Rm #:	7. Org.
Almami Jawara	02/25/04	04-0124	—	301-925-0569	1052B	Infrastr

8. CCR Title: Ram Upgrade on p0vcs02 EIN# 0326

9. Originator Signature/Date **Almami Jawara /s/ 2/24/04**	10. Class II	11. Type: CCR	12. Need Date: Feb 27,2004

13. CCR Sponsor Signature/Date **Byron V. Peters /s/ 2/24/04**	14. Category of Change: Other	15. Priority: (If "Emergency" fill in Block 27). Routine

16. Documentation/Drawings Impacted *(Review and submit checklist):*	17. Schedule Impact: N/A	18. CI(s) Affected:

19. Release Affected by this Change: 6A	20. Date due to Customer: N/A	21. Estimated Cost: None - Under 100K

22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☐Other:

23. Problem: (use additional Sheets if necessary)
Poor system performance due to low memory.
Sun SPARCstation 20 (1 X 390Z50)
socket J0201 has a 32MB SIMM
socket J0202 has a 64MB SIMM
sockets J0304/J0407 have a 4MB VSIMM installed for SX (CG14) graphics
empty sockets: J0303 J0301 J0305 J0203 J0302
total memory = 96MB

24. Proposed Solution: (use additional sheets if necessary)

Add an additional 256MB of RAM to P0vcs02

25. Alternate Solution: (use additional sheets if necessary)

.
None

26. Consequences if Change(s) are not approved: (use additional sheets if necessary)
System performance will be compromised

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF ☒PVC ☐VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL
☐EOC ☐ IDG Test Cell ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. SCDV CCB Chair (Sign/Date): **Byron V. Peters /s/ 02/26/04**	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
33. EDF CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS

CM01JA00 Revised 10/2/03   ECS/EDF/SCDV